



ROLL SERVO




MOUNTED AT F.S. 85.5

NOTE 1: REFER TO MANUFACTURER'S DOCUMENTATION  
NOTE 2: DASHED LINES ARE EXISTING WIRES  
NOTE 3: CAP AND STOW  
NOTE 4:  
NOTE 5:

A/P COMPUTER



PITCH SERVO



MOUNTED AT F.S. 135.75

| COASTAL WINDS<br>AVIONICS                                                              |              | DESCRIPTION       |           |
|----------------------------------------------------------------------------------------|--------------|-------------------|-----------|
| CRS 70AR637D<br>8400 AIRPORT BLVD<br>MOBILE, AL. 36608<br>251-410-8050<br>www.cwa.aero |              | GFC 500 AUTOPILOT |           |
| DRAWN BY                                                                               | DATE         | AC MAKE           | AC TAIL#  |
| D.DEVILBISS                                                                            | 17 JULY 2023 | GLASAIR           | N991RM    |
| INSPECTED BY                                                                           | DATE         | AC MODEL          |           |
| J.THEOBALD                                                                             | 17 JULY 2023 | GLASAIR III       |           |
| LEAD INSTALLER                                                                         | DATE         | AC S/N            | DRAWING # |
| T.LONG                                                                                 | 17 JULY 2023 | DB-1              | 23128-130 |